PROLEVALL 29

ANODIZED ALUMINIUM WITH SELF-ADHESIVE AND PUNCHED

transition profiles



ANODIZED ALUM. with adhesive thermo packed bar length 2.7 lm - pack. 40 Pcs - 108 lm

| | 40 PCS - 106 IIII | |
|---|-------------------|---------------------|
| Article | HxLmm | |
| PLV 29A | 5,5 X 29 | |
| ANODIZED ALUM. with bar length 0,83 lm - pack | | no packed SELF PACK |
| Article | HxLmm | |
| PLV 298AS | 5,5 X 29 | |
| ANODIZED ALUM. with bar length 0,93 lm - pack | | no packed SELF PACK |
| Article | HxLmm | |
| PLV 299AS | 5.5 X 29 | |
| | 3,3 K 23 | |
| ANODIZED ALUM. with bar length 1,03 lm - pack | h adhesive thern | no packed SELF PACK |
| | h adhesive thern | no packed SELF PACK |



ANODIZED ALUM. punched thermo packed bar length 2.7 lm - pack. 40 Pcs - 108 lm

| bar length 2,7 lm - pack | . 40 Pcs - 108 lm | |
|---------------------------------|---|-------------|
| Article | HxLmm | |
| PLV 29F | 5,5 X 29 | |
| | d with screws and screw anchor ength 0,83 lm - pack. 20 Pc | SELF PACK |
| Article | HxLmm | |
| PLV 298FS | 5,5 X 29 | |
| | d with screws and screw anchor ength 0,93 lm - pack. 20 Pc | SELF PACK |
| Article | HxLmm | |
| PLV 299FS | 5,5 X 29 | |
| | d with screws and screw anchor ength 1,03 lm - pack. 20 Pc | S SELF PACK |
| Article | HxLmm | |
| PLV 2910FS | 5,5 X 29 | |
| | | |


Available in the colours: AA - AO (AB, AT, CH e SB available on demand with a minimum quantity order of 100 pcs). The code of the selected colour must be added to the article code. E.g.: PLV... 29A (chosen colour anodized gold alum.) PLVAO 29A.

COLOURS




AVAILABLE MINIMUM QUANTITY 100 PCS by color and height





EXAMPLES AND INSTRUCTIONS FOR LAYING METHODS



Adhesive version

1. Choose the suitable profile and cut it to the necessary length.
2. Degrease, wash and clean the solid surface thoroughly.
3. Remove the protective paper from the adhesive. 4. Lay the profile by applying pressure evenly over the whole surface without using a hammer.

Punched version

Choose the suitable profile and cut it to the necessary length.
 Mark the position of the holes using the existing holes in the profile as reference.
 Insert the screw anchors into the drilled holes.
 Fix the profile using flathead screws suitable for the relative slots

4. Fix the profile using flathead screws suitable for the relative slots in the profile.

PROLEVALL 33 is a transition profile in extruded polished brass, available in the self-adhesive or punched versions. It is used to give a clean-cut, elegant finish when joining and compensating differences in level of floors that are already laid and in differing or same materials e.g. ceramic tiles-wood-parquet-marble, etc. It joins and compensates a thickness between 4 and 6mm. **PROLEVALL 33** ensures a perfect finish with little height, covering any flaws created during laying, while the contoured edges guarantee perfect adherence to the floor.

PROLEVALL 33

POLISHED BRASS WITH SELF-ADHESIVE AND PUNCHED

POLISHED BRASS with adhesive thermo packed bar length 2.7 lm - pack, 20 Pcs - 54 lm

PLVOL 3310AS

| | . 20 Pcs - 54 Im | |
|---|---|---------------------|
| Article | HxLmm | |
| PLVOL 33A | 5,5 X 33 | |
| POLISHED BRASS with bar length 0,83 lm - pag | | packed SELF PACK |
| Article | HxLmm | |
| PLVOL 338AS | 5,5 X 33 | |
| | | |
| | | packed SELF PACK |
| POLISHED BRASS with bar length 0,93 lm - pac Article | | packed SELF PACK |
| bar length 0,93 lm - pac | k. 20 Pc | packed SELF PACK |
| bar length 0,93 lm - pac Article | H x L mm 5,5 X 33 h adhesive thermo | PACK |

5,5 X 33

POLISHED BRASS punched thermo packed bar length 2,7 lm - pack. 20 Pcs - 54 lm

| Article | HxLmm | | |
|--|--|---|--------------|
| PLVOL 33F | 5,5 X 33 | | |
| POLISHED BRASS punched thermo packed - bar l | | | ELF PACK |
| Article | HxLmm | | |
| PLVOL 338FS | 5,5 X 33 | | |
| Article | H x L mm | | |
| POLISHED BRASS punched thermo packed - bar l | | | SELF PACK |
| | | | |
| PLVOL 339FS | 5,5 X 33 | 1 | |
| PLVOL 339FS POLISHED BRASS punched | 5,5 X 33 with screws and scre | | SELF |
| PLVOL 339FS POLISHED BRASS punched | 5,5 X 33 with screws and scre | | |
| PLVOL 339FS POLISHED BRASS punched thermo packed - bar lo | 5,5 X 33 with screws and screength 1,03 lm - pack | | |
| PLVOL 339FS POLISHED BRASS punched thermo packed - bar leader to the place of the p | 5,5 X 33 with screws and screength 1,03 lm - pack | | |
| PLVOL 339FS POLISHED BRASS punched thermo packed - bar le | 5,5 X 33 with screws and screength 1,03 lm - pack | | SELF |

PLVOL 33A
PLVOL 33BAS
PLVOL 3310AS
PLVOL 3310AS
PLVOL 33F
PLVOL 33F
PLVOL 339FS
PLVOL 339FS
PLVOL 3310FS
H 5,5 mm

EXAMPLES AND INSTRUCTIONS FOR LAYING METHODS



- 1. Choose the suitable profile and cut it to the necessary length. Adhesive version
- Degrease, wash and clean the solid surface thoroughly.
 Remove the protective paper from the adhesive.
 Lay the profile by applying pressure evenly over the whole surface without using a hammer.

Punched version

2. Mark the position of the holes using the existing holes in the profile as reference. **3.** Insert the screw anchors into the drilled holes. **4.** Fix the profile using flathead screws suitable for the relative slots in the profile.

transition profiles